

NOTICE TO INSTALLER OF CB(X)27UH-048 AND -060 UNITS

When this kit (83M57 -- LB-109844A) is being used on CB(X)27UH-048 and -060 units, a new indoor coil top seal cap is required. The replacement top cap (Part number 603115-01) is available separately from your local warehouse. The replacement cap can also be requested by calling the Technical Support Department at 1-800-453-6669.

580161-01

NOTICE TO INSTALLER OF CB(X)27UH-048 AND -060 UNITS

When this kit (83M57 -- LB-109844A) is being used on CB(X)27UH-048 and -060 units, a new indoor coil top seal cap is required. The replacement top cap (Part number 603115-01) is available separately from your local warehouse. The replacement cap can also be requested by calling the Technical Support Department at 1-800-453-6669.

580161-01

NOTICE TO INSTALLER OF CB(X)27UH-048 AND -060 UNITS

When this kit (83M57 -- LB-109844A) is being used on CB(X)27UH-048 and -060 units, a new indoor coil top seal cap is required. The replacement top cap (Part number 603115-01) is available separately from your local warehouse. The replacement cap can also be requested by calling the Technical Support Department at 1-800-453-6669.

580161-01

NOTICE TO INSTALLER OF CB(X)27UH-048 AND -060 UNITS

When this kit (83M57 -- LB-109844A) is being used on CB(X)27UH-048 and -060 units, a new indoor coil top seal cap is required. The replacement top cap (Part number 603115-01) is available separately from your local warehouse. The replacement cap can also be requested by calling the Technical Support Department at 1-800-453-6669.

580161-01