



DESCRIPTION	
KEY	COMPONENT
J3	JACK-UNIT ECONOMIZER
J16	JACK-UNIT
K43,-1	RELAY-ECON. HEAT
P3	PLUG-LESS ECONOMIZER
P16	PLUG-UNIT
TB1	BLOCK-TERMINAL

--- LOW VOLTAGE FIELD WIRING  
 \_\_\_\_\_ FACTORY WIRING

WIRING DIAGRAM 09/12	
ACCESSORIES	
CB17/CBH17 ACCESSORIES RELAY KIT	
Supersedes Form No. 529,143W	
Form No. 533,752W	

0912

