



SERVICE AND APPLICATION NOTES

C-15-09
November 6, 2015

14ACX-042, -048 / 4AC14L42, 48 Replacement Outdoor Coil Part Number / Catalog Number Correction

ISSUE:

For a period of time, the Bill of Materials for the affected units listed an incorrect part number and catalog number for replacement outdoor coils. The coil dimensions shown were also incorrect. The **incorrect** information is shown below.

Catalog Number	Part Number	Part Description	Coil Dimensions (inches)
24W93	LB-87170DC	Repair Part Coil Assembly	27 x 27 x 36 (2 row)

AFFECTED UNITS:

MODELS
14ACX-042-230A15, 14ACXS042-230A15
14ACX-042-230A16, 14ACXS042-230A16
14ACX-048-230-15, 14ACX-048-230-16, 14ACX-048-230-17
4AC14L42P-6A, 4AC14LS42P-6A, 4AC14LR42P-6A, 4AC14B42P-6A, 4AC14BR42P-6A
4AC14L42P-7A, 4AC14LS42P-7A, 4AC14LR42P-7A, 4AC14B42P-7A, 4AC14BR42P-7A
4AC14L48P-6A
4AC14L48P-7A, 4AC14B48P-7A

FIELD ACTION:

The Bill of Materials for the affected units has been corrected. When ordering replacement outdoor coil assemblies for the affected units, use the part number and catalog number shown below.

Catalog Number	Part Number	Part Description	Coil Dimensions (inches)
14S64	LB-87170EN	Repair Part Coil Assembly	27 x 27 x 32 (2 row)