



## ADDENDUM

508225-01  
08/2021

### **Addendum to Installation Instructions for Indoor Coil Replacement Kits used with Air Handlers – 13Y Series Replacement Coils**

Due to supply shortages of the foam used to line the indoor coil drain pan during manufacture, the coil replacement procedure has temporarily changed.

Two options have been approved and are outlined below.

- **Option 1:** Reuse the existing drain pan. If the existing pan is intact and in good shape, use it in place of the new pan provided with the kit.
- **Option 2:** Utilize the new drain pan in the kit by field installing installer-provided foam to the bottom of the drain pan.

Install the replacement coil as outlined in the kit instruction.

